



ER APP ATC 68 — Enable Controller workstation to indicate when aircraft systems indicates an RA occurrence.

Provide alerting to relevant Controllers HMI when a/c under their responsibility are indicating an ACAS RA.

Category SYSTEM

Stakeholder Air Navigation Service Provider

Civil

Civil ATS Approach Service Provider

Civil ATS En-Route Service Provider

V3 End 31-12-2014

V4 Start -

V5 Start -

V4 End -

V5 End 31-12-2015

Air Navigation Service Provider: -

Civil

Civil ATS Approach Service

Provider: -

Civil ATS En-Route Service


Provider: -

IOC 31-12-2019

FOC 31-12-2023

Context

Related Elements



OI Operational Improvement Steps

Code	Benefits start date (IOC) - Full benefit date (FOC)																																													
	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40																				
ER APP ATC 68		▲																																												
CM-0802																																														

EN Dependent Enablers

Relationship	Code	Title	Related Elements
Is synchronised with	A/C-48a	Air broadcast of aircraft position/vector (ADS-B OUT) compliant with DO260B	STK OI EN DS
Enabled by	REG-HNA-01	Extension of the ACAS mandate	OI EN DS
Enabled by	REG-HNA-02	Regulatory Provisions on ATC Procedures to provide a common response to down linked airborne TCAS/ACAS alerts	OI EN DS

PCP PCP Elements: No associated data

STK Stakeholders

Code	Title	Related Elements
ANSP	Air Navigation Service Provider	EN
ANSP-CIV-APP	Civil ATS Approach Service Provider	EN
ANSP-CIV-ER	Civil ATS En-Route Service Provider	EN

Standards: No associated data

OBJ Implementation Objectives: No associated data

Stakeholder Lines of Action (SLoAs): No associated data

PJ SESAR Workpackages: No associated data